



# COMPLETION REPORT NGAT 003


YILLI RREUNG HOUSING ABORIGINAL CORPORATION ICN: 4241 | ABN: 48 983 249 337

# Contents



Details of Dwelling	3
Summary	4
Construction Photos	6

Plumbing Certification 19





Prepared By: John Adams Alicia Briston



20

# Summary



The house is a 4-bedroom 1 bathroom house which has now been transformed into a house with an extended outdoor living area. The house has also received plumbing and electrical upgrades including new electrical fittings, lights and fans. New tiles in newly painted bedrooms and living area. New screen doors to the main living area are enclosed with new screens that are also fitted to the front and rear entrances, the existing bedroom doors and new entrance sets fitted to all bedrooms.



New stainless wardrobes have been fitted to each bedroom with new screens and louvre galleries fitted throughout the entire house. A new deck was constructed on the front of the existing deck giving extra outdoor deck space 6.5m x 9m. Externally the screens on all windows were replaced. A new set of stairs and handrails to the front and existing deck. New roof rafters and a new roof with existing hot water service being used but all piping upgraded to meet requirements and the rear veranda roof was raised to look even with the rest of the house





#### Some of the major works performed included:

- Construction of the new verandah over the new deck
- New screens fitted to the living area side of the house to enclose it
- All new bathroom fixtures and plumbing
- New deck sectioned constructed
- New louvre galleries fitted throughout
- · New verandah rafters fitted above bathroom ceiling
- New doors and entrance sets throughout entire house
- Switchboard upgrade and new electrical fittings



- ASC Compliance
- Full On Plumbing
- S&L Painting Services
- DICE Electrical
- M&D Roofing and Construction
- Dekmar Design and Construction
- Steeline GRP
- Rhino Industrial
- Trade Building Supplies
- NTF
- Palmerston Paint Supplies
- Apex Steel
- Hireworks
- Top End Steel
- Totalweld
- Bunnings



## **Kitchen Before**

The old kitchen area before the installation of the new kitchen and kitchen wall





# Kitchen After Installation of the new kitchen





New wall panel for the kitchen and concrete slab installed with the roof line at the rear now level with the rest of the house





### **Bedrooms Before**

The old bedrooms before repainting, tiles and new electrical fittings that were dull and uninviting







# **Bedrooms After**







# **Living Area Before**



You can also see in the above picture the living area flooring and before the rear screens and doors are fitted

### **Living Areas After**

### New living area with screens









All steel is painted in rust conversion and rust preventative paint to prevent further corrosion and the deck was constructed out of termite treated LVL timber. The new screen door gives a new security level to the house with a new wall panel for the kitchen

#### **Deck**

The below picture shows the old deck removed and the empty space before the new deck installation. The removal and replacement of the existing window louvre channels was necessary because of rust and proximity to the ocean



**Before** 



After

Deck & Verandah Before

New deck and verandah extension under construction





Verandah After
New light fittings on the verandah





#### **Roof Before**

As you can see in these pictures the extent of the corrosion in the roof rafters. These were replaced and a new roof structure erected





Roof After
The roof was replaced with new colorbond sheets





# Rear verandah roof raised for better alignment



