Completion Report

Homelands Housing and Infrastructure Program



*HHIP00002 Mungkarta Housing and Infrastructure Upgrades

House No 1







Contents

Project Summary	3
Scope of Works Overview	
Visual Progress	8
Approved Variations	14
Attachments	15
Final Review and Acceptance	16

Service Provider	Barkly Plumbing Services	ABN	39 255 240 990
Contact Details	Mrs Sarah Curran Mob 0438 384 324 Email sarah@barklyplumbing.com.au	Contractor Accreditation Limited (CAL) Registration Number:	19414
Project Name	Mungkarta Homeland Housing Upgrade Program	Contract No.	MUNG00002
Homeland	Mungkarta	Community ID	244
Project Type	Housing upgrades	House #	1
Commencement Date	15/10/24	Completion Date	17/3/25







Project Summary

Include a brief summary of the deliverables on the project. Also include a photo of handover back to residents on completion of the project, if applicable.

The deliverables were focused on the essential repairs and reconstruction of House 1, with a priority given to the 9 HLPs. Our aim is to provide sustainable, healthy, and safe living conditions. We have repaired and improved House 1 to address the critical needs of the occupants as you can see		
below.		

Scope of Works Overview

Homeland:	Mungkarta
House/Asset No:	1
Scoping Date:	29/4/24

Throughout the Dwelling

Posy resin broken tile throughout

Install new Tile tread and riser

Repair fence

Check solar repair/replace

Install new Wall paint indoor throughout

Install new Ceiling paint indoor throughout

Install new Outdoor paint

Pest control Before

Pest control After

Removalist out

Removalist back in

Clean before construction

Cleaning after construction

Outdoor

Replace garden tap

Raise ORG

Import dirt to cover footing and clean 3m strip around the house

Remove tree

Replace Bird board where required

Test earth

Upgrade switch board to Standards

splash pad for garden tap 600m x 600m

Install new clothesline

Front Veranda

Install new Handrail

Install new Solid sheeting to handrail at 1200mm high with 100mm gap at bottom

Install new Wind break with perforated colorbond

Install new Install gate

Replace lights

Replace light switch

Install New Fan

Install new Fan Switch



Completion Report

Back Veranda

Install new Handrail

Install new Solid sheeting to handrail at 1200mm high with 100mm gap at bottom

Install new Wind break with perforated colorbond

Replace Light 1200 LED

BARKLY PLUMBING SERVICES

Install new gate

Replace lights

Replace light switch

Install New Fan

Install new Fan Switch

Kitchen

Install new Double bowl sink in existing bench

Replace Tapware

Plumbing

Install new Stainless-steel draws

Install new Stainless-steel shelves

Install new Stainless-steel Pantry (double)

Move switch for oven to appropriate location

Install new tile splash back

Install new floor tile

Install new tile skirting

Replace all windows (including 1 combination)

Replace all doors

Replace screen door

Install new stove

Install new Smoke detectors if required/where required

Install new lights

Install new light switch

Install new Fan

Install new Fan Switch

Repair wall

Install new Curtain Rail

Install new door between corridor and kitchen

Install new GPOs

Living

Install new Stainless-steel Pantry / Powder coated

Replace all windows (including 1 combination)

Replace all doors

Replace screen door

Install new Smoke detectors if required/where required

Install new lights



Completion Report

Install new light switch Install new Fan Install new Fan Switch Install new Curtain Rail Install new GPO for A/C Install new GPOs

Corridor

Install new GPOs

Bathroom

Replace all windows (DIPL standard wet area)

Replace all doors

Install new lights

Install new light switch

Install new shower rail

Install new Curtain Rail

Install new toilet

Install new basin

Install new basin tapware

Install new soap Holder

Replace breech with mixer

Install new shower rose to correct height

Install new 600 Stainless Steel Shelves

Install new wall tiles

Install new floor tiles

Install new waterproofing

Install new GPOs

Laundry

Fix laundry door frame

Install new tapware

Install new tub

Install new Skirting

Install new floor tiles

Install new GPOs

Install new SS shelves

Outside Laundry

Install new tile tread and riser

Install new Additional external GPO

Install new SS shelves

Hallway

Replace door

Replace window 1

Completion Report

Install new lights Install new light switch Install new additional shelving

Bedroom 1

Replace all windows (including 1 combination)

Replace all doors

Install new lights

Install new light switch

Install new Fan

Install new Fan Switch

Install new Stainless-steel Pantry / Powder coated

Install new Curtain Rail

Install new GPO for A/C

Install new Skirting

Install new GPOs

Bedroom 2

Replace all windows (including 1 combination)

Replace all doors

Install new lights

Install new light switch

Install new Fan

Install new Fan Switch

Install new Stainless-steel Pantry/Power coated

Install new Curtain Rail

Install new GPO for A/C

Install new Skirting

Install new GPOs

Bedroom 3

Replace all windows (including 1 combination)

Replace all doors

Install new lights

Install new light switch

Install new Fan

Install new Fan Switch

Install new Stainless-steel Pantry / Powder coated

Install new Curtain Rail

Install new GPO for A/C

Install new Skirting

Install new GPOs



Visual Progress

Include before and after images of all areas that received upgrades. Delete/add areas as needed.

BEFORE

AFTER

Front Exterior





Side Exterior









Back Exterior





Kitchen







Bedroom 1





Bedroom 2







Bedroom 3





Bathroom







Toilet





Laundry







DEFECT RECTIFICATION






Silicone and paint



Clothes line



Laundry taps

Painting



HANDOVER REPORT

Project Details			
Name of Project	HHIP Mungkarta Housing Upgrade		
House #	1		
Contact Person	Corentin Gigot	Contact Number	0429 477 404
Email	projects@barklyplumbing.com.au manager@barklyplumbing.com.au		



Doc Ref	Title	Issue Date	Revision Status	Next Revision Date
TWSFRM013	PROJECT REPORTING TEMPLATE	11/07/2024	VOR00	11/07/2025
NOTE: This document is deemed UNCONTROLLED when printed				