



Pandayal - Homelands and Housing Infrastructure Program - House 04


NORTH00010



YILLI RREUNG HOUSING ABORIGINAL CORPORATION
ICN: 4241 | ABN: 48 983 249 33

Contents

Details of Works	3.
Contractors	4.
Summary	5.
Construction Photos	7.
Certificates	14.




Details of Works



PANDAYAL


ENTRANCE
±4KM FROM
CHANEL POINT ROAD
IN AT L AT

Community:	Pandayal Community
House Number:	House 04
Asset No / Lot No:	House 04
Contract No / Project No:	NORTH00010



Contractors

- Blackstar Contracting
- Yilli Rreung Housing Aboriginal Corporation
- Off Grid




Summary

The housing and infrastructure improvement works concentrated on the repair, maintenance, and replacement of key household hardware to ensure that homes within the community remain safe, functional, and suitable for residents. These upgrades were undertaken to support tenants in maintaining safe and healthy living environments.

A major focus of the program was the identification and completion of urgent repairs and maintenance tasks that could pose potential safety risks or impact the day-to-day functionality of the homes. Addressing these issues helped improve the overall condition and reliability of the properties.


The works also prioritised the assessment and restoration of essential health hardware within each dwelling. Ensuring that these systems and fixtures are working correctly enables tenants to carry out everyday healthy living activities, including maintaining hygiene, safe food preparation, and general household use.

Overall, these improvements were aimed at strengthening the safety, functionality, and quality of housing infrastructure, ensuring homes within the community provide a secure and healthy environment for tenants.



Completed scope of works included:

- New power system installed
- carport installed 10 metres x 6 metres



Contruction Photos



