# **Completion Report**

# Homelands Housing and Infrastructure Program



# \*HHIP00002 Mungkarta Housing and Infrastructure Upgrades

\*House No 7\*







# **Contents**

Project Summary	3
Scope of Works Overview	
Visual Progress	8
Approved Variations	13
Attachments	14
Final Review and Acceptance	15

Service Provider	Barkly Plumbing Services	ABN	39 255 240 990
Contact Details	Mrs Sarah Curran Mob 0438 384 324 Email sarah@barklyplumbing.com.au	Contractor Accreditation Limited (CAL) Registration Number:	19414
Project Name	Mungkarta Homeland Housing Upgrade Program	Contract No.	MUNG00002
Homeland	Mungkarta	Community ID	244
Project Type	Housing upgrades	House #	7
Commencement Date	12/9/24	Completion Date	19/11/24



**Completion Report** 



# **Project Summary**

Include a brief summary of the deliverables on the project. Also include a photo of handover back to residents on completion of the project, if applicable.

The deliverables were focused on the essential repairs and reconstruction of House 7, with a priority given to the 9 HLPs. Our aim is to provide sustainable, healthy, and safe living conditions. We have repaired and improved House 7 to address the critical needs of the occupants as you can see below.		

## Scope of Works Overview

Homeland:	Mungkarta
House/Asset No:	7
Scoping Date:	29/4/24

#### Throughout the Dwelling

Replace solar

Front door to open opposite way

Install new Wall paint indoor throughout

Install new Ceiling paint indoor throughout

Install new Outdoor paint

Pest control Before

Pest control After

Removalist out

Removalist back in

Clean before construction

Cleaning after construction

#### Outdoor

Replace garden tap

Replace stairs

Install new 1200x1200 landing

Install new Dog proof fence where required

Import dirt to cover footing and clean 3m strip around the house

Remove tree

Replace Bird board where required

Test earth

Upgrade switch board to Standards

Install new splash pad for garden tap 600x600

Install new wall fan (new install)

Install new clothesline

#### **Left Front Veranda**

Remove window bedroom window and make wall

Enclose veranda and make as extra bedroom

Remove stairs no access from outside

Install new lights


Install new light switch

Install new Fan

Install new Fan Switch

Install new GPOs

Install new Curtain rail





#### Install new window (Combination)

#### **Right Front Veranda**

Install new Handrail

Install new Solid sheeting to handrail at 1200 high with 100mm gap at bottom

Install new Wind break with perforated colorbond

Install new gate

Replace lights

Replace light switch

Install New Fan (new)

Install new Fan Switch (new)

#### **Back Veranda**

Install new Handrail

Install new Solid sheeting to handrail at 1200 high with 100mm gap at bottom

Install new Wind break with perforated colorbond

Replace Light 1200 LED

Repair flashing

Replace lights

Replace light switch

Install New Fan (new)

Install new Fan Switch (new)

Repair stairs

South wall close wall matching existing

Install new GPOs

#### Kitchen

Install new SS bench

Install new Double bowl sink

Replace Tapware

Install new Plumbing

Install new Stainless-steel draws

Install new Stainless-steel shelves

Install new Stainless-steel Pantry

Move switch for oven to appropriate location

Install new tile splash back

Install new floor tile

Install new tile skirting

Replace all windows (Standard)

Replace all doors

Replace screen

Install new stove

Install new Smoke detectors if required/where required

Install new lights

Install new light switch

Install new Fan



**Completion Report** 

Install new Fan Switch Install new Curtain Rail Install new GPOs

#### Living

Install new Stainless-steel Pantry/Power coated

Replace all windows (Including 1 combination)

Replace all doors

Replace screens

Install new Smoke detectors if required/where required

Install new lights

Install new light switch

Install new Fan

Install new Fan Switch

Install new Curtain rail

Install new GPO for A/C

repair roof leak where required

Replace 50% of the ceiling where required

Install new GPOs

#### **Bathroom**

Replace all windows (DIPL standard wet area)

Replace door

Install new lights

Install new light switch

Install new shower rail

Install new Curtain Rail

Install new toilet

Install new basin

Install new basin tapware

Install new Bath

Install new mixer

Install new Holder

Replace breech with mixer

Install new shower rose to correct height

Install new 600 Stainless Steel Shelves

Install new wall tiles

Install new floor tiles

Install new waterproofing

Install new mirror

#### **Outside Toilet**

Install new toilet complete

Install new lights

Install new light switch

Install new basin and tapware

**Completion Report** 

Install new tile floor

#### **Outside corridor**

Install new screen door Install new light (wall)

#### **Outside trough**

Clean trough

Install new tapware

GPO not working investigate and repair

Install new SS Shelves

#### Corridor

Install new ceiling

Install new man hole

Repair wall

Install new Booster switch

#### Bedroom 1

Replace all windows (Including 1 combination)

Replace door 1

Install new lights

Install new light switch

Install new Fan

Install new Fan Switch

Repair wall

Install new Stainless-steel Pantry/Power coated

Install new Curtain Rail

Install new GPO for A/C

Install new Gpos

#### Bedroom 2

Replace all windows (Including 1 combination)

Replace doors

Install new lights

Install new light switch

Install new Fan

Install new Fan Switch

Install new Stainless-steel Pantry/Power coated

Install new Curtain Rail

Install new GPO for A/C

Install new GPOs

#### **Bedroom 3**

Replace all windows (Including 1 combination)

Replace door

Install new lights
Install new light switch
Install new Fan
Install new Fan Switch
Install new Stainless-steel Pantry/Power coated
Install new Curtain rail
Install new GPOs

# **Visual Progress**

Include before and after images of all areas that received upgrades. Delete/add areas as needed.























## AFTER / DURING





























**Completion Report** 

# **Approved Variations**

Variation for plumbing